- 1) Bias T circuitry will need to be designed by the end user.
- 2) The 710 mount uses a 10K3A thermistor. The Steinhart-Hart constants are

C1x10<sup>-3</sup>: 1.129241 C2x10<sup>-4</sup>: 2.341077 C3x10<sup>-7</sup>: 0.877547